
MolP Firmware v4.3.0.8 Release Notes

Intended for use with Control4 Driver v300.

Products impacted

- MolP B-900 Series
- MolP B-960 Series

Improvements

- All B-960 devices now pull an IPv4 DHCP IP address as well as an existing link-local address. This change facilitates a wider variety of Picture-in-Picture devices and ensures compatibility outside of existing brands, since some cameras do not respond to the IPv4 Link Local communication.
- IR has been overhauled to emulate Control4 controllers. This resolves most issues with double IR presses and channel presets.

Fixes

- Fixes to the HTTPS engine to resolve issues where the controller was online in OvrC but the HTTPS web UI was inaccessible.
- Fixes to v1 and v2 EDID not reverting after changing to 4K30 HDR.